

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

0	1	G A B I H 1												2	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5																						
7	8	LICENSEE CODE												14	LICENSE NUMBER												25	LICENSE TYPE												30	CAT Su												57

CON'T

REPORT
SOURCE

REPORT SOURCE: 0 1 7 8

DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE: 0 1 2 3 4 5 6 7 8 9

REPORT DATE: 0 1 2 3 4 5 6 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Prior to the ISI RPV Hydro, Plant Review Board meeting number 79-169 was held

0 3 | with three alternates. Administrative procedure HNP-6 and T.S.6.5.1.3 specify that no





0 4 | more than two alternates may constitute a quorum. There were no personnel injuries,

0 5 | radiation exposures or effects to public health and safety. This is a non-repetitive

0 6 | occurrence.

07 | Page

0 3 | _____

(17) LER NO. REPORT NUMBER: 79
 EVENT YEAR: 79
 SEQUENTIAL REPORT NO.: 052
 OCCURRENCE CODE: 03
 REPORT TYPE: L
 REVISION NO.: 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	Z	25	Z	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The designated alternate for the Superintendent of Plant Engineering Services did
1 1 | not realize that the quorum requirements of T.S.6.5.1.3 and administrative procedure
1 2 | HNP-6 were violated when Plant Review Board meeting number 79-169 was called with
1 3 | three alternates. The corrective action taken was to re-review in Plant Review Board
1 4 | meeting number 79-181 the material originally (continued)

80

FACILITY STATUS (28) 1 5 H 28

% POWER 0 0 0 29

OTHER STATUS (30) N/A

METHOD OF DISCOVERY (31) Z 31

DISCOVERY DESCRIPTION (32) N/A

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 32 2 34 N/A N/A

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	3	N/A	

POOR

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
7	8	9	10	11	12
					N/A

ORIGINAL

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		1																																																																																															

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY	
2	5	N	44	N/A			

NAME OF PREPARED C. L. Cogain, Supt. Plt. Eng. Serv. PHONE 912-367-7781

827 154

7908240 377

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Cause Description and Corrective Actions (continued)

reviewed in Plant Review Board meeting number 79-169, and to review the quorum and alternate member requirements with the members of the PRB and their normal alternates.