

TIC

JUL 13 1979 9:18

RECEIVED

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

August 8, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 530A  
PO/FHT:scj  
Docket No. 50-339  
License No. CPPR-78

Subject: IE Bulletin 79-13 Amended Response

Dear Mr. O'Reilly:

Our July 13, 1979, letter, Serial no. 530, in response to IE Bulletin 79-13, "Cracking in Feedwater System Piping", stated that the North Anna Unit 2 feedwater piping had been inspected on June 27, 1979. This is incorrect, as only the steam generator inlet nozzles have been inspected to date. The remaining inspection effort will be completed in a timely manner consistent with the requirements of the subject bulletin.

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

935076

7909100 214

790300  
A

OFFICIAL COPY