



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS LOUISIANA 70174 • (504) 386-2345

August 31, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11904
Q-3-A35.07.12
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Docket No. 59-382
Final Report of Significant
Construction Deficiency No. 12
"Material Failure - Pipe Fittings -
4" - 45° Ell and 4" - 90° Ell"

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are submitting two copies of the final report for the subject Significant Construction Deficiency.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

Enclosure

- cc: 1) Director ✓
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with 15 copies of report)
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with one copy of report)

3019
S/11
934 163

7909100 323