

BALTIMORE GAS AND ELECTRIC COMPANY

GAS AND ELECTRIC BUILDING
BALTIMORE, MARYLAND 21203

ARTHUR E. LUNDVALL, JR.
VICE PRESIDENT
SUPPLY

July 6, 1979

U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Docket Nos. 50-317/50-318
License Nos. DPR-53/DPR-69

Attention: George H. Smith, Chief
Fuel Facility and Materials
Safety Branch


Subject: Combined Inspection 50-317/79-04; 50-318/79-04

Gentlemen:

This refers to your letter of June 25, 1979 in response to our letter of April 27, 1979.

Enclosure 1 to this letter completes the corrective and preventive actions previously documented in our response of April 27, 1979.

Very truly yours,



for A. E. Lundvall, Jr.
Vice President - Supply

Enclosure

333214

7909110167

ENCLOSURE 1

REPLY TO NRC LETTER DATED JUNE 25, 1979 IN REFERENCE
TO COMBINED INSPECTION 50-317/79-04; 50-318/79-04

ITEM A - Corrective Action

Current copies of applicable laboratory methods approved as required have been placed in the files of the Environmental Engineering Group as of July 6, 1979.

ITEM B - Corrective Action

The RMC laboratory method for Sr-89, Sr-90 analyses in fish bone has been modified to include larger sample size and increased count time. On this basis it is expected that beginning with the samples of fish taken after July 1, 1979 the required detection limits for Sr-89, Sr-90 will be achieved.

ITEM C - Corrective Action

The offsite farms at locations 15 and 16 are owned and operated by independent farmers, who alone determine what crops are available and when they are harvested. BG&E has instructed its personnel to improve liaison with these farmers to ensure that the required samples are obtained at harvest time.

933215