



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

August 31, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11903
Q-3-A35.07.06
Q-3-A35.07.10
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Status of Significant Construction Deficiencies
No. 6 "Emergency Diesel Generators - Defective Shafts and Springs"
No. 10 "Defective Emergency Generator Roller Pin"

REFERENCE: a) LP&L Letter, LPL 10343 dated December 29, 1978
b) LP&L Letter LPL 10233 dated December 5, 1978 -
as amended by LPL 10316 dated December 19, 1978

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(a), LP&L has previously submitted interim reports of the two Significant Construction Deficiencies concerning the emergency diesel generators. Based on communications with Cooper-Bessemer, the manufacturer of the diesel generators, LP&L reported in the referenced letters that modifications correcting the deficiencies were scheduled to be completed and final reports submitted by August 31, 1979.

Cooper-Bessemer has now informed us that the last of the modification assemblies are now planned for shipment from the factory by September 7, 1979. This delay by Cooper-Bessemer does not adversely impact Waterford 3 construction needs and is acceptable.

Based on the above, we will now submit final reports for Significant Construction Deficiency No. 6 and No. 10 by November 1, 1979.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

336238

Boia
5/10

7909120 503

5

Mr. K. V. Seyfrit

2

August 31, 1979

cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

336239