



Consumers
Power
Company

Stephen H. Howell
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

September 12, 1979
Howe-247-79

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT -
UNIT NO 1, DOCKET NO 50-329
UNIT NO 2, DOCKET NO 50-330
DROP-IN ANCHORS

In accordance with the requirements of 10 CFR 50.55(e), this letter constitutes an interim report on the status of installed Hilti Drop-In Anchors which did not meet the tension testing requirements.

The attachments to this letter provide a description of the discrepancy, potential safety implications, investigation and planned corrective actions.

Another report, either interim or final, will be sent on or before October 12, 1979.

WRB/lb

- Enclosures: 1. Quality Assurance Program, Management Corrective Action Report, MCAR-1, Report 34, dated August 21, 1979
2. Letter, J A Rutgers to G S Keeley, MCAR-34 Interim Report #1, dated September 5, 1979.

CC: Director of Office of Inspection & Enforcement
Att: Mr Victor Stello, USNRC (15)

✓ Director, Office of Management
Information & Program Control, USNRC (1)

B019
S/1

7909140370

943211