

CMW-PSL  
Ltr. Bk. 684

Copies to: CMW, JHB, CAW, NGR, DAS

Offsite: ADS, JRB, COW, MAS, REU, KNH

To: Mr. J. P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Atlanta, Georgia 30303

From: Mr. C. M. Wethy, Plant Manager  
St. Lucie Plant - DPR 67  
Florida Power & Light Company  
Miami, Florida

Subject: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM PROMPT  
REPORTABLE OCCURRENCE 335-79-30

USNRC  
ATLANTA



79 OCT 5

September 19, 1979

This memo confirms our telephone notification of the subject 14-day reportable occurrence made on September 18, 1979 to Mr. J. Dyer of your office.

During the inspection/evaluation of pipe restraints/supports in accordance with NRC I & E Bulletin 79-14, two restraints on ECCS piping systems were found to be in non-conformance. Restraint SI-676-429 on line 4"-SI-416 (vertical riser section) was found as a U-bolt type restraint which would prohibit movement in both the North-South and East-West directions. By design it should permit movement in the East-West direction.

A restraint on line 6"-SI-464 (horizontal section) which is designed to prohibit lateral and vertical movement was found missing. In its place was pipe hanger SIH-99 which is suspended from the ceiling above.

Both restraint errors have been corrected. The U-bolt at restraint SI-676-429 has been replaced with a unidirectional restraint that permits East-West movement. New restraint SI-868-6099 has been fabricated and installed on line 6"-SI-464 to prohibit vertical and lateral movement.

*C. M. Wethy*  
C. M. Wethy, Plant Manager  
St. Lucie Plant

CMW:cwc

*App 2  
9/10*

7910150 493

OFFICIAL COPY

1152 007