



**Consumers  
Power  
Company**

Stephen H. Howell  
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

October 12, 1979  
Howe-267-79

Mr J G Keppler, Regional Director  
Office of Inspection and Enforcement  
US Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT  
UNIT NO 1, DOCKET NO 50-329  
UNIT NO 2, DOCKET NO 50-330  
UNIT NO 1, REACTOR VESSEL BROKEN ANCHOR BOLT

In accordance with the requirements of 10 CFR 50.55(e), this letter constitutes an interim report on the status of the broken anchor bolt in the Unit 1 reactor vessel support skirt flange.

The attachment to the letter provides a description of the condition and planned investigation.

Another report, either interim or final, will be sent on or before December 14, 1979.

WRB/w1

Attachment: Broken Reactor Vessel Anchor Bolt in Unit 1 Status Report

CC: Director of Office of Inspection & Enforcement  
Att: Mr Victor Stello, USNRC (15)

Director, Office of Management  
Information and Program Control, USNRC (1)

1152 153

7910160 269