

## UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-286

UNIT NAME Indian Point 3DATE 10/3/79COMPLETED BY C. ConnellTELEPHONE (914) 739-8200REPORT MONTH September

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
34	790901	S	63.8	A	1	N/A	HH	HTEXCH	River Water leakage through Condenser tubes to hotwells. Plugged leaking tubes.
35	790906	F	11.4	A	3	N/A	HH	Pump XX B	Loss of #32 MBF pump. Cleaned control oil orifices.
36	790914	S	385.4	C	1	N/A	N/A	N/A	Refueling Outage

<sup>1</sup> F: Forced  
S: Scheduled

<sup>2</sup> Reason:  
A-Equipment Failure (Explain)  
B-Maintenance or Test  
C-Refueling  
D-Regulatory Restriction  
E-Operator Training & License Examination  
F-Administrative  
G-Operational Error (Explain)  
H-Other (Explain)

<sup>3</sup> Method:  
1-Manual  
2-Manual Scram.  
3-Automatic Scram.  
4-Other (Explain)

<sup>4</sup> Exhibit F - Instructions  
for Preparation of Data  
Entry Sheets for Licensee  
Event Report (LER) File (NUREG-  
0161)

<sup>5</sup> Exhibit G - Same Source

7910300 207

(9/77)

1240-323

POOR ORIGINAL