

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C B E P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 1 0 0 2 7 9 8 1 0 2 3 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While attempting to establish RHR service water flow for an engineering evaluation, the  
0 3 operator could not get the E11-F068B valve to open. This is the RHR Service Water flow  
0 4 control valve for the "B" loop subsystem.  
0 5 Technical Specifications 3.7.1.1, 6.9.1.9b  
0 6  
0 7  
0 8

0 9 SYSTEM CODE SH 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 7 9 21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN B 33 FUTURE ACTION A 34 EFFECT ON PLANT Z 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 0 37 40  
ATTACHMENT SUBMITTED N 41 NPRD-4 FORM SUB. N 42 PRIME COMP. SUPPLIER A 43 COMPONENT MANUFACTURER G 0 8 0 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 An investigation showed that relay RI in the position modulator had contacts sticking,  
1 1 causing the valve to see a constant "close" signal. As the relay is a sealed unit, the  
1 2 contacts were freed by tapping the relay body by hand. A replacement relay has been  
1 3 placed on order. This is considered an isolated event, however, relay operation will  
1 4 be monitored to ensure its proper operation until replacement.

1 5 FACILITY STATUS E 28 % POWER 0 9 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Surveillance 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 6 RELEASED OF RELEASE Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

NAME OF PREPARER A. C. Tollison, Jr.

PHONE 919-457 9521

7910310 402

1214 175

026-1-1600