

REF INT

PUBLIC SERVICE ELECTRIC AND GAS COMPANY
Salem Nuclear Generating Station
P. O. Box 56
Hancocks Bridge, New Jersey 08038

September 10, 1979

Mr. Boyce H. Grier
Director of USNRC
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Sir:

REPORTABLE OCCURRENCE 79-58/01P
SALEM NO. 1 UNIT LER

This letter will serve to confirm our telephone report to Mr. Gary Schneider of the Regional NRC office on Friday, September 6, 1979, advising of a potential reportable occurrence in accordance with Technical Specification 6.9.1.8.

We have been notified by our Engineering Department that a Westinghouse conducted review of the environmental qualifications of Westinghouse supplied NSSS equipment has identified that conditions associated with high energy line breaks inside or outside containment and their impact on non-safety control systems may constitute an unreviewed safety question. The control systems concerned are steam generator power operated relief valve control, pressurizer power operated relief valve control, main feedwater control and automatic rod control systems.

A detailed report will be submitted in the time period specified by the Technical Specifications.

Very truly yours,

Original Signed By

H. J. Midura
Manager - Salem Generating Station

AWK:jds

CC: General Manager - Electric Production
Manager - Quality Assurance

POOR ORIGINAL

1268 282

7911050 076