

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 30, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - EXCESSIVE OUTPUT FLUCTUATIONS
OF FOXBORO INSTRUMENTATION - NCR SWP 79-S-5 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. J. Gouge on August 28, 1979, in accordance with 10 CFR 50.55(e).
An interim report was submitted on September 26, 1979. Enclosed is
our second interim report. We expect to submit our next report by
February 7, 1980.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1289 337

Borg
5/11