

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 1 0 0 4 7 9 1 1 1 0 2 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1100 on October 4, 1979, #11 Component Cooling Heat Exchanger was
0 3 removed from service to perform corrective maintenance on the operator
0 4 for the Heat Exchanger Saltwater outlet valve (1-CV-5206). The problem
0 5 with the operator was corrected and the Heat Exchanger was returned
0 6 to operation at 1455, October 4, 1979. (T. S. 3.7.3.1). This is not
0 7 a repetitive occurrence.

0 8
0 9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Valve 1-CV-5206 would not open until a 20% open electrical signal was
1 1 generated from its controller. This was due to its faulty current to
1 2 pneumatic converter. The converter was recalibrated and valve position
1 3 switches were adjusted. The valve had been operational from a safety
1 4 outside standpoint. No preventive action is deemed necessary.

1 5
1 6
1 7
1 8
1 9
2 0
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

NAME OF PREPARER R. Heibel/P. Rizzo

PHONE (301) 234-7943/7986

NRC USE ONLY