

**Detroit
Edison**

Edward Hines
Assistant Vice President
Quality Assurance

3331 W. Big Beaver Road
Troy, Michigan 48064
(313) 649-7123

October 23, 1979

EF2-50,629

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Detroit Edison Response to IE Bulletin 79-23

This is in response to your letter onocket 50-341, dated September 12, 1979, together with IE Bulletin 79-23. This IE Bulletin describes potential failure of emergency diesel generator (EDG) field exciter transformer.

The Enrico Fermi Unit 2 EDG's have Wye-Wye connected exciter power supply transformers and are not susceptible to third harmonic inducted circulating currents from the generator. Also, Fermi 2 has committed in the EF2 FSAR, Appendix A, to follow USNRC Regulatory Guide 1.108, Revision 1, for the EDG preoperational and surveillance test program.

If you require any additional action by us on this matter, please advise us.

Very truly yours,

Edward Hines

cc: Office of Inspection and Enforcement
Division of Reactor Operations Inspection
U.S. Nuclear Regulatory Commission
Washington D.C. 20555

1301 234

OCT 26 1979

7911090074