

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 O H D B S 1 2 0 0 - 0 0 N P F - 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 - 0 3 4 6 7 1 0 0 1 7 8 8 1 0 2 7 7 8 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 0625 hours on 10/1/78, during performance of surveillance testing, the calculated  
0 3 value for unidentified Reactor Coolant System (RCS) leakage exceeded the 1 GPM limit  
0 4 by 0.08 GPM. This placed the unit in the Action Statement of Technical Specification  
0 5 (T.S.) 3.4.6.2. At 0730 hours on 10/1/78, the increased leakage was identified by a  
0 6 measurement of the Reactor Coolant Pumps standpipe leak-off. This reduced the uniden-  
0 7 tified leakage to 0.54 GPM, and removed the unit from the Action Statement of T.S.  
0 8 3.4.6.2. The small leakages were processed through the normal containment sump. 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE (NP-33-78-118)  
C 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR 7 8 21 22  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 Z 25 Z Z Z Z 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Increased Reactor Coolant Pump seal leakage is the cause of this occurrence. Investi-  
1 1 gation into the possibility of installing more accurate seal leakage indication is  
1 2 continuing per Facility Change Request 78-357.  
1 3  
1 4

1 5 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
G 28 0 0 0 29 NA B 31 Surveillance Test ST 5042.02  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 NA NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED DESCRIPTION 45  
N 44 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
DVR 78-153 NAME OF PREPARER Scott Fulmer PHONE 419-259-5000, Ext. 276  
781103 0158

NRC USE ONLY