



THE ELECTRIC COMPANY

KANSAS GAS AND ELECTRIC COMPANY

DEENN L. KOESTER
VICE PRESIDENT OPERATIONS

January 24, 1980

Mr. W.C. Seidle, Chief
Reactor Construction and
Engineering Support Branch
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Re: Docket No. STN 50-482
Subj: Interim 50.55(e) Report
Concrete Block Walls

Dear Mr. Seidle:

On December 19, 1979, Mr. Maurice Clark, KG&E Manager
Quality Assurance (Site), notified Reactor Inspector
Mr. Oberg of a construction deficiency which now appears
to be reportable under 10CFR50.55(e).

Attached is an interim report regarding the construction
deficiency. A final report is expected to be completed
by May 1, 1980.

Yours very truly,

Deenn L. Koester

GLK:bb
Attach

cc: Director Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
Attach 15 Cys

1829 327

800 129 0 408

BO19
SE
1/1

S