

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

0 1 L 6 0 5 0 0 0 0 2 9 8 7 1 1 2 9 7 9 8 1 2 2 8 7 9 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 The suppression chamber inboard vent isolation valve (PC-230MV) would not operate

0 3 with the control switch and there was no position indication in the control room.

0 4 PC-245AV valve was operable for redundancy. No adverse consequences from the stand-

0 5 point of public health and safety occurred since PC-230MV is normally closed.

0 6

0 7

0 8

0 9 S D E X V A L V O P X Z  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

1 7 7 9 0 3 9 0 3 L 0  
7 8 9 10 11 12 13 14 15 16 17 18  
LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO

C H Z Z 0 0 0 0 N 2 N L 2 0 0  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Consultation with Limitorque did not reveal cause. Failures have only occurred

1 1 under shock and vibration conditions. These conditions did not exist on this valve.

1 2 Analysis of this failure was random failure. The rotor was replaced with a quali-

1 3 fied part.

1 4

1 5 E 0 8 7 NA B Operator Observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 Z Z NA NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 0 0 0 Z NA 1829 008  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 0 0 0 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 Z NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 N NA 8 0 0 1 2 9 0 5 0 6 NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PUBLICATION ISSUED DESCRIPTION

NAME OF PREPARER Jerry L. Scheer

PHONE 402-825-3811

POOR ORIGINAL