



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

PRODUCTION DEPARTMENT

January 25, 1980

Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

POOR ORIGINAL

ATTENTION: Mr. J. P. O'Reilly, Director

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station
Docket Nos. 50-416/417
File 0272/0498/15525/15526
Final Report for PRD-79/11
as Defined in 10 CFR 50.55(e)
AECM-80/30

On July 9, 1979, Mr. J. K. Rausch of your office was notified of a potentially reportable deficiency concerning a problem with cracked control device assemblies on Gould 4.16 KV Switchgear, 6.9 KV Switchgear and 480 Volt Load Centers. It was determined that this is not a reportable deficiency within the meaning of 10 CFR 50.55(e). Details of our findings are described in the attached report.

Yours truly,

L. F. Dale
Nuclear Project Manager

1866.322

JRF/JDR:dwe
Attachment

cc: Mr. N. L. Stampley
Mr. R. B. McGehee
Mr. T. B. Conner

Mr. Victor Stello, Jr., Director
Division of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

bcc: Dr. D. C. Gibbs
Mr. Adrian Zaccaria
Mr. J. N. Ward
Mr. D. M. Lake
Mr. R. L. Scott
Mr. W. L. Nail
Mr. J. P. McGaughy
Mr. T. E. Reaves
Mr. C. K. McCoy
Mr. J. W. Yelverton
Mr. A. R. Smith
File

3019
3/1