



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000
January 25, 1979

2-019-16

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/78-29, 50-368/78-30
and 50-368/78-32
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning the RCS temperature dropping to 107°F within 52 minutes exceeding 100°F/hr. limit per Tech. Specs. (ROR No. 78-29), the reactor being manually tripped at 1°F below the 525°F Tave as required by Tech. Specs. (ROR No. 78-30) and the inoperability of an Emergency Feedwater Train (ROR No. 78-32).

Very truly yours,

Daniel H. Williams
Manager, Licensing

DHW:REI:ce
Attachment

cc: Mr. John G. Davis, Acting Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management Information
& Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

7901310043