

CONTROL BLOCK:

--	--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7902050185

REPORTABLE OCCURRENCE 250-78-17
LICENSEE EVENT REPORT
PAGE TWO

Additional Cause Description and Corrective Action

Corrective action will include repair of the defect and evaluation of cover pressure control and monitoring methods.

Tank Data: 13,000 ft³
15 psig internal pressure
200°F
0 psig external pressure