

Unit 2

LICENSEE EVENT REPORT

Report No. 2-79-28/3L

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1															2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																															
7		8		14														25										26										30										57										58									
				LICENSEE CODE														LICENSE NUMBER																				LICENSE TYPE																													

CON'T

REPORT SOURCE L 6 0 5 0 - 0 2 7 7 1 0 5 2 4 7 9 8 0 6 2 2 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During surveillance testing, a redundant low level HPCI start signal
0 3 | from LSL-2-3-72C was found inoperable. A wire to the HPCI start relay
0 4 | was erroneously disconnected during modification work performed on
0 5 | 5/21/79. Safety significance is minimal since the three other redundant
0 6 | channels were operable.

08 789

SYSTEM CODE S F (11)		CAUSE CODE A (12)		CAUSE SUBCODE X (13)		COMPONENT CODE Z Z Z Z Z (14)				COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 2 8 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE L (20)		REVISION NO. 0 (21)		ACTION TAKEN F (22)		FUTURE ACTION Z (23)	
EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 0 (26)		ATTACHMENT SUBMITTED Y (27)		NPRD-4 FORM SUB. N (28)		PRIME COMP. SUPPLIER Z (29)		COMPONENT MANUFACTURER Z 9 9 9 (30)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the occurrence was human error. A drafting mistake caused

1 1 | an incorrect wiring modification to be performed resulting in the

1 2 | inoperability of the redundant HPCI start signal. The field wiring and

1 3 | connection drawing were corrected. An investigation of the event is be-

1 4 | ing performed by Engineering QA. People responsible were interviewed.

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 C (28) 0 6 9 (29) N/A B (31) Surveillance Test
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 Z (33) Z (34) N/A
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	

PERSONNEL INJURIES		2170 003	
NUMBER	DESCRIPTION (41)		
1	N/A	POOR ORIGINAL	

1		2		3		4		5		6		7		8		9		10		11		12						
LOSS OF OR DAMAGE TO FACILITY																												
TYPE		DESCRIPTION																										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24					
		Z	(42)	N/A																			7906280118 S					

7 4 9 10
PUBLICITY
ISSUED (2) (1) (N) (44) DESCRIPTION (45) N/A NRC USE ONLY
68 69 70

NAME OF PREPARER

M. J. Cooney

PHONE

(215) 841-5020

NRC USE ONLY

054-926