

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

JUN 25 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 1 - FLEXIBLE BELLOWS PENETRATIONS OF STEEL
CONTAINMENT VESSEL MISALIGNED DURING INSTALLATION - NCR 1666 -
FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Bill Cottle on May 25, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our first interim report. We expect to submit our next report by September 11, 1979.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

2146 067

3019
S 1/1