

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

REPORT SOURCE: L 6 0 5 0 0 0 3 6 6 7 1 1 2 0 3 7 8 8 1 1 2 2 2 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

1 With the reactor in the Run mode, the D. C. output breaker of 2R44-S003 (Static

2 Inverter for 2R24-S018B) tripped. The inverter being inoperable is a violation of

3 Technical Specification 3.8.2.1. Public health and safety nor safe plant operation

4 were affected as the alternate supply for 2R24-S018B was operable.

5

6

7

8

9

SYSTEM CODE: E D 11

CAUSE CODE: E 12

CAUSE SUBCODE: G 13

COMPONENT CODE: G E N E R A 14

COMP. SUBCODE: F 15

VALVE SUBCODE: Z 16

EVENT YEAR: 7 8 21 22

SEQUENTIAL REPORT NO.: 0 7 7 24 25

OCCURRENCE CODE: 0 3 28 29

REPORT TYPE: L 30

REVISION NO.: 0 32

LER RO REPORT NUMBER: 17

ACTION TAKEN: A 18

FUTURE ACTION: Z 19

EFFECT ON PLANT: Z 20

SHUTDOWN METHOD: Z 21

HOURS: 0 0 0 0 37 40

ATTACHMENT SUBMITTED: N 23

NPRD-4 FORM 1 SUB.: N 24

PRIME COMP. SUPPLIER: A 25

COMPONENT MANUFACTURER: E 3 5 15 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 The D. C. output breaker tripped because the 'A13A12' (A. C./ D. C. Protection) card,

2 located in the inverter, failed. The 'A13A12' card was replaced and the inverter was

3 returned to service within the 8 hour time period given in Technical Specification

4 3.8.2.1.a.

5

6

7

8

9

FACILITY STATUS: B 28

% POWER: 0 6 4 29

OTHER STATUS: NA 30

METHOD OF DISCOVERY: A 31

DISCOVERY DESCRIPTION: Operator Observation 32

ACTIVITY CONTENT RELEASED OF RELEASE: Z 33

AMOUNT OF ACTIVITY: NA 35

LOCATION OF RELEASE: NA 36

PERSONNEL EXPOSURES NUMBER: 0 0 0 37

TYPE: Z 38

DESCRIPTION: NA 39

PERSONNEL INJURIES NUMBER: 0 0 0 40

DESCRIPTION: NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42

DESCRIPTION: NA 43

PUBLICITY ISSUED: N 44

DESCRIPTION: NA 45

NRC USE ONLY

NAME OF PREPARER: R. T. Nix

Superintendent of Maintenance

PHONE: (912) 367-7781

7901030125