

TEAA
50-327
328

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

DEC 19 1978

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - REDUCED SIS ACCUMULATOR FLOW
AT LOW REACTOR COOLANT SYSTEM LEVELS - NCR 1011 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector J. K. Rausch on September 18, 1978, and an interim report was transmitted to your office on October 17, 1978. Enclosed is our second interim report. We will transmit our next report to your office by March 9, 1979.

If you have any questions concerning this matter, please get in touch with M. R. Wisenburg at FTS 854-2581.

Very truly yours,


for J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

7901250094

5

780068