



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 29, 1979

2-019-19

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/78-33 and 50-368/78-34  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning an inoperable Containment Building Pressure Channel and the improper installation of an Excore Detector Channel.

Very truly yours,

Daniel H. Williams  
Manager, Licensing

DHW:BI:vb

Attachment

cc: Mr. John G. Davis, Acting Director  
Office of Inspection & Enforcement  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management Information  
and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

7902050112