

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ARANO 00-000000-00 41111 (5)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T
01 L 05000368 7123078 0112979 (9)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 During Mode 3 operation, PPS "C" Containment Building Pressure
03 transmitter failed to 60 psia. There were no consequences. Effected
04 trips were bypassed. There have been no similar occurrences. Reported
05 per T.S.6.9.1.9.(b). Requirements of Action Statement Table 3.3-3,
06 Action 9 & 10 were met.
07
08
09

SYSTEM CODE AA (11) CAUSE CODE E (12) CAUSE SUBCODE E (13) COMPONENT CODE INS (14) COMP. NUM. CODE T (15) VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LER/RO REPORT NUMBER 718 (17) EVENT YEAR 718 (18) SEQUENTIAL REPORT NO. 033 (19) OCCURRENCE CODE 03 (20) REPORT TYPE L (21) REVISION NO. 0 (22)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTION TAKEN B (23) FUTURE ACTION Z (24) EFFECT ON PLANT Z (25) SHUTDOWN METHOD Z (26) HOURS 000 (27) ATTACHMENT SUBMITTED N (28) NPD-4 FORM SUB N (29) PRIME COMP. SUPPLIER N (30) COMPONENT MANUFACTURER F180 (31)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 The current-to-current transmitter was dissassembled with no problems
11 noted. Appears to be an isolated failure. Transmitter was
12 returned to service and removed trips from bypass.
13
14

FACILITY STATUS B (32) % POWER 000 (33) OTHER STATUS Power Ascension (34) METHOD OF DISCOVERY A (35) DISCOVERY DESCRIPTION NA (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT Z (37) RELEASED OF RELEASE Z (38) AMOUNT OF ACTIVITY NA (39) LOCATION OF RELEASE NA (40)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL EXPOSURES
NUMBER 000 (41) TYPE Z (42) DESCRIPTION NA (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL INJURIES
NUMBER 000 (44) DESCRIPTION NA (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOSS OF OR DAMAGE TO FACILITY
TYPE Z (46) DESCRIPTION NA (47)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PUBLICITY
ISSUED N (48) DESCRIPTION NA (49)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519

790205 0116