

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: 919-457-6701

LER CONTINUATION -- RO# 2-79-1

Facility: BSEP Unit #2

Event Date 1/2/79

refueling outage. A plant modification (77-269) to permanently replace this type of instrument with a more accurate and stable analog instrument has been written. Installation of the modification is scheduled for the 1980 refueling outage. This analog instrument change-out is expected to eliminate the set point drift events experienced to date.