

# LICENSEE EVENT REPORT

CONTROL BLOCK:                      (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 00-000000-000 3 41111 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T  
01 L 6 05000237 7 052879 8 061579 9  
7 8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 During normal operation, the 125V DC switch No. 2, "Reserve Feed, Bus 22,"  
03 was opened during ground checks on Unit 2 turbine building main bus. As  
04 a result, 2B2 recirc. MG set oil pump tripped, followed by a trip of the 2B  
05 recirc. MG set. The A MG set speed was reduced <65% as required by the Technical  
06 Specifications (Sec. 3.6.H.4). No Technical Specifications for the reactor  
07 parameters were exceeded, and, therefore the safety significance of this event was  
08 minimal.  
7 8 9

09 C B 11 A 12 A 13 C K T B R K 14 E 15 Z 16  
7 8 9 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 12 13 COMPONENT CODE 14 15 COMP. SUBCODE 16 17 VALVE SUBCODE 20 21  
17 79 039 03 L 0  
7 8 9 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32  
X X B Z 0000 N N A C770  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 Opening switch #2 resulted in a loss of control power to the 2B recirc. MG  
11 set causing it to trip. Switch #2 was reclosed immediately, and 2B recirc. MG set  
12 restarted. Switch #2 was marked to caution against opening. No similar event  
13 encountered in the past.  
7 8 9

14 E 096 NA B Operator observation  
7 8 9 FACILITY STATUS 10 11 % POWER 12 13 OTHER STATUS (30) 44 45 METHOD OF DISCOVERY 46 47 DISCOVERY DESCRIPTION (32) 80  
15 Z Z NA NA  
7 8 9 ACTIVITY CONTENT 10 11 RELEASED OF RELEASE 12 13 AMOUNT OF ACTIVITY (35) 44 45 LOCATION OF RELEASE (36) 80  
16 000 Z NA  
7 8 9 PERSONNEL EXPOSURES 10 11 NUMBER 12 13 TYPE 14 15 DESCRIPTION (39) 80  
17 000 Z NA  
7 8 9 PERSONNEL INJURIES 10 11 NUMBER 12 13 DESCRIPTION (41) 80  
18 Z NA  
7 8 9 LOSS OF OR DAMAGE TO FACILITY 10 11 TYPE 12 13 DESCRIPTION (43) 80  
19 N NA  
7 8 9 PUBLICITY 10 11 ISSUED 12 13 DESCRIPTION (45) 80  
20 N NA 7906220373  
7 8 9 NAME OF PREPARER Atif A. Ammar PHONE 421  
NRC USE ONLY

2348 026