

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	3	2	4	7	0	5	2	1	7	9	8	0	6	1	5	7	9	9
60	61	DOCKET NUMBER						62	69	EVENT DATE						74	75	REPORT DATE						80

02 While performing PT 12.2c, Diesel Generator #3 Monthly Load Test, it was noticed that

[b] (3) when the speed was lowered to 60 hz., the engine "failed to start" alarm would

04 energize and the service water valve would shut. This would make diesel generator #3

05 | inoperable. This is the first time we have had this problem.

06 | Technical Specifications 3.8.1.1, 6.9-1.9b.

0	7
---	---

0	8	
---	---	--

09		SYSTEM CODE EE		11	CAUSE CODE E		12	CAUSE SUBCODE G		13	COMPONENT CODE INSTRU						14	COMP. SUBCODE E		15	VALVE SUBCODE Z		16			
7	8	5	6	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
17		LER/RO REPORT NUMBER		EVENT YEAR 79		—		SEQUENTIAL REPORT NO. 038		—		OCCURRENCE CODE 03		REPORT TYPE L		—		REVISION NO. 0								
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER										
E		Z		Z		Z		0000		N		Y		A		A121										
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The switches in both Airpox tachometer switch boxes drifted upward causing the diesel
---	---	---

11 to have speed/frequency problems. Both switches were calibrated per Maintenance

12 | Instruction 3-18 and the diesel was returned to service. This is considered an

13 | isolated event and no further action is required. These switches are in the

1 4 | preventative maintenance program.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	G	28	0	0	0	29	NA				B	31	Periodic Test					
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA				NA									
PERSONNEL EXPOSURES				PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				PUBLICITY							
NUMBER				NUMBER				TYPE				DESCRIPTION							
1	7	0	0	0	37	Z	38	NA				7906220409							
PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				PUBLICITY				NRC USE ONLY							
NUMBER				NUMBER				TYPE				DESCRIPTION							
1	8	0	0	0	40	NA				9062204									
LOSS OF OR DAMAGE TO FACILITY				PUBLICITY				NRC USE ONLY											
TYPE				TYPE				DESCRIPTION				DESCRIPTION							
1	9	Z	42	NA				790622044											
PUBLICITY				NRC USE ONLY															
ISSUED				ISSUED				DESCRIPTION				DESCRIPTION							
2	0	N	44	NA				790622044											

NAME OF PREPARER Mr. A. C. Tollison, Jr.

PHONE: (919) 457-6701