

LICENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6

LICENSEE NAME C B E P I														LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0											LICENSE TYPE 4 1 1 1 1					EVENT TYPE 0 3	
CATEGORY 57 58		REPORT TYPE L		REPORT SOURCE L		DOCKET NUMBER 0 5 0 - 0 3 2 5											EVENT DATE 1 1 2 4 7 7					REPORT DATE 1 2 0 9 7 7									

EVENT DESCRIPTION

With the reactor at power, in the RUN mode, while moving the spent fuel cask out of the reactor building, after the inner railroad doors were opened and the cask was positioned between the inner and outer railroad doors, a security alarm was received indicating that the outer doors were not shut securely.

(Technical Specification 3.7.c.1)

SYSTEM CODE 2 2		CAUSE CODE E		COMPONENT CODE Z Z Z Z Z Z Z					PRIMARY COMPONENT SUPPLIER A		COMPONENT MANUFACTURER X 9 9 9					VIOLATION N	
10		11		12					43		44					48	

R01-77-96

CAUSE DESCRIPTION

The outer door latching mechanism is faulty. The outer doors were chained and latched. The inner doors were closed and sealed. Materials are on order to repair the latching mechanism for the doors. When the materials arrive, a service

(See attached)

FACILITY STATUS E		POWER 0 9 9			OTHER STATUS NA			METHOD OF DISCOVERY A		DISCOVERY DESCRIPTION (See attached)				
9		10			13			44		46				
FORM OF ACTIVITY RELEASED Z		CONTENT OF RELEASE Z			AMOUNT OF ACTIVITY NA			LOCATION OF RELEASE NA						
5		10			11			44		45				

PERSONNEL EXPOSURES

NUMBER 0 0 0		TYPE Z		DESCRIPTION NA	
11		12		13	

PERSONNEL INJURIES

NUMBER 0 0 0		DESCRIPTION NA	
11		12	

OFFSITE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE Z		DESCRIPTION NA	
10			

PUBLICITY

NA

ADDITIONAL FACTORS

7904060406

This is being reported under Technical Specification Section 6.11.2.b (2)

LER CONTINUATION -- RO# 1-77-96

Facility: BSEP Unit #1

Event Date 11-24-77

CAUSE DESCRIPTION CON'T:

representative of the door manufacturer will complete the door repairs.

Both sets of doors are chain locked from the inside and a sign was placed on the door stating that shift foreman and security approval is required prior to unlocking the doors.