

7-10-79

715 Edney Building

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

August 24, 1979

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

POOR ORIGINAL

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-260/7918

The enclosed report provides details concerning a loss of indicating  
lights for FCV 2-64-21, reactor building to torus vacuum breaker, during  
normal operation. This report is submitted in accordance with Browns  
Ferry unit 2 Technical Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

Acc 2  
S/11

7908280732