


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	E	C	P	R	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 2 9 8 7 0 7 0 6 7 9 8 0 0 0 3 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (1G)

0 2 | During routine testing, reactor vessel level indicating switch NBI-LIS-58A switch num-
0 3 | ber one was found with a trip point less conservative than allowed in Tech. Spec. Table
0 4 | 3.2.A. There was no significant occurrence as a result of this event. The redundant
0 5 | level switch NBI-LIS-58A was operable. There were no adverse affects to public health
0 6 | and safety. This event is repetitive. Reference LER 79-5, 77-12
0 7 |
0 8 |
7 8 9

SYSTEM CODE C D 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14		COMP SUBCODE S 15		VALVE SUBCODE Z 16	
7 8		9 10		11 12		13 18		19 20			
LER/RO REPORT NUMBER 17		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 1 8 24 26		OCCURRENCE CODE / 27		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED N 23	
33 34		35 36		37 40		41 42		43 44		45 47	
NPRD-4 FORM SUB. 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER Y 0 1 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A Yarway Model 4418C level indicating switch failed to actuate within tolerance. In-

1 1 vestigation disclosed that sediment consisting of dust and moisture in the auxiliary

1 2 switch mechanism had caused the switch to hang-up. The switch was cleaned and after

1 3 cleaning tested satisfactorily. A new mechanical cam actuated solid state switch

1 4 module is under evaluation.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	5	29	NA	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
ROUTINE SURVEILLANCE TESTING									

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	(37)	Z	(38)	NA	

		7	8	9	11	12	13		
		PERSONNEL INJURIES							
		NUMBER				DESCRIPTION			
1	2	10	10	10	10	10	NA	(41)	

[illegible][illegible]

ISSUED (2) (0) (N) (44) DESCRIPTION (45) NA

7 8 9 10 68 69 80

PUBLICITY NPC USE ONLY

NAME OF PREPARER David Phillips

PHONE: 402-825-3811

NRC USE ONLY

0261-1032(199207)10:3<201::AID-JCOP201>3.0.CO;2-#