

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M A P P S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T
0 1 REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 1 0 2 6 7 9 8 1 1 2 6 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 At 1815 hrs. on October 26, 1979 the Reactor Coolant Leak Detection Air Sampling
0 3 System (C-19) tripped. On investigation the operator found the breaker on Panel
0 4 P-6 tripped and sampler motor hot.
0 5
0 6
0 7
0 8

0 9 SYSTEM CODE C I 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE M O T O R X 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Sampler motor overheated causing breaker to trip. Breaker was reset and unit
1 1 continued to run without a re-occurrence.
1 2
1 3
1 4

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32 OPERATOR INVESTIGATION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER G. G. WHITNEY

PHONE: 617-746-7900