




NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Thyro-Cat, LLP 227 Union Avenue Holbrook, NY 11741 REPORT NUMBER(S) 2019-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 030-35758	4. LICENSE NUMBER(S) 31-30650-01	5. DATE(S) OF INSPECTION September 25 and October 17, 2019	
LICENSEE: <p>The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:</p> <p><input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.</p> <p><input checked="" type="checkbox"/> 2. Previous violation(s) closed.</p> <p><input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.</p> <p style="margin-left: 40px;">Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):</p> <p style="margin-left: 40px;">_____</p> <p><input checked="" type="checkbox"/> 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)</p> <p style="margin-left: 40px;">(Continued on NRC Form 591M Part 2)</p>			
Statement of Corrective Actions			
<p>I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.</p>			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Sharon Eisen, D.V.M.		10/22/19
NRC INSPECTOR	Penny Lanzisera/Jonathan Pfingsten		10-18-19
BRANCH CHIEF	Donna Janda		10/30/19

*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WBL Documents\WBL Inspection Records\R31-30650-01.2019001.591M-Part1.doc

SUNSI Review Completed By: _____

/ RA / PL

☒ Public ☒ Non-Sensitive

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED; Thyro-Cat, LLP 227 Union Avenue Holbrook, NY 11741 REPORT NUMBER(S) 2019-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 030-35758	4. LICENSE NUMBER(S) 31-30650-01	5. DATE(S) OF INSPECTION September 25; October 17, 2019	

(Continued)

Condition 15 of NRC License 31-30650-01 requires, in part, that the licensee conduct its program in accordance with the statements, representations, and procedures contained in the documents listed in the license, including the letter dated November 10, 2011.

The letter dated November 10, 2011, Section I, Item 3, requires, in part, that licensee employees monitor hands and clothing for contamination after each procedure or before leaving the area.

Contrary to the above, as of September 25, 2019, licensee employees did not monitor hands and clothing for contamination after each procedure or before leaving the area in accordance with their license commitments. Specifically, licensee employees donned dedicated shoes to wear in restricted areas and surveyed the area of use but did not survey their hands or clothing prior to leaving the treatment area. On October 17, 2019, the licensee's Radiation Safety Officer reinstructed staff on proper surveys and revised the daily survey forms to include documentation of personnel surveys.

This is a Severity Level IV violation (Section 6.3).