

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 T N C N P 1 2 0 0 - 0 0 0 0 0 - 0 0 7 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 55

ONLY 1 L 6 0 5 0 0 0 3 2 7 7 0 4 2 5 8 1 8 0 5 1 9 8 1 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 With unit in Mode 4 at 330° F and 350 PSIG, the auxiliary building vent particulate

3 monitor (RM-90-101A) declared inoperable. The plant entered action statement

4 44 of LCO 1.3.3.10. There was no effect on public health or safety. No previous

5 occurrences.

6 _____

7 _____

8 _____

80

9 M C 11 E 12 E 13 M O T O R X 14 Z 15 Z 16

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 3 1 2 0 4 7 0 3 1 0

LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 G 0 6 3

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

0 The slow speed filter paper drive motor failed. The cause of the failure was

1 diagnosed as normal wear. The motor was replaced and the monitor returned to

2 service at 0900 CST on 4/25/81.

3 _____

4 _____

80

5 G 28 0 0 0 29 NA 30 A 31 Operator observation 32

FACILITY STATUS % POWER OTHER STATUS ALTHOUGH IT DISCOVERY DISCOVERY DESCRIPTION

6 Z 33 Z 34 NA 35 NA 36

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

7 0 0 0 37 Z 38 NA 39

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

8 0 0 0 40 NA 41

PERSONNEL INJURIES NUMBER DESCRIPTION

9 Z 42 NA 43

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

0 N 44 NA 45

PUBLICITY SUED DESCRIPTION

NRC USE ONLY

80

Name of Person: M. R. Harding/ A. M. Wilkey

Phone: (615) 842-8317

8105270099