

May 20, 1981

PRN-LI-81-242

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-81-09
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: APRIL 20, 1981
TECHNICAL SPECIFICATION 3.5
PROCEDURE INADEQUACY



The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,


A.D. Schmidt
Vice President
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

8106010394

5