

CONTROL BLOCK:

--	--	--	--	--	--

1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	9	8	7	0	3	2	0	8	1	8	0	4	1	6	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

FILED DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Reactor Building Closed Cooling Water Pump 1D tripped during start and was out of
03 service for about 6 hours. Remaining 3 RBCCW pumps were operable. This event was re-
04 petitive. Redundant systems were operable. This event presented no adverse effects
05 upon public health and safety.

06 _____

0	7	
---	---	--

0	8	
---	---	--

7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 11 12 13 14 15 16

9 10 11 12 13 14 15 16

17	LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO.		
		8	1	—		0	0	5	/	0	3	0	
		21	22	23	24	25	26	27	28	29	30	31	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
A		X		Z		Z		0 0 0 0		N		A	
33	34	35	36	37	38	39	40	41	42	43	44	45	46
COMPONENT MANUFACTURER													
1		2		0		2							
47		48		49		50		51		52		53	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Undersized fuse was installed on a ITE size 4 motor starter control circuit of RCCW.
---	---	--

1	1	Pump 1D. A spare size 4 starter was bench tested and its in-rush current measured &
---	---	---

1 2 found to be the same as subject starter. Control fuses in all size 4 starters on 1

1	3	ECCS components were checked & undersized fuses replaced. Equipment history records
---	---	---

1 4 did not indicate similar problems with sizes 1,2,&3 motor starters.

FACILITY STATUS (1) (5) (F) (28) % POWER (0) (9) (5) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 3.3 2 3.4 NA NA

PERSONNEL EXPOSURE NUMBER TYPE DESCRIPTION (a)

1 7 0 0 0 37 Z 38 NA

PERSONNEL INJURIES		80
NUMBER	DESCRIPTION	
0000	NA	

10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
10		11		12		13		14		15		16		17		18		19		20		21		22																																																																																																																					

2 0		N 44		NA		NRC USE ONLY									
-----	--	------	--	----	--	--------------	--	--	--	--	--	--	--	--	--

NRC USE ONLY

NAME OF PREPARER L. F. Bednar

PHONE: 402-825-3811

8106030 248