

CONTROL BLOCK:          ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | O | F | S | V | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 2 | 0 | 4 | 5 |

7 8 9 14 15 25 26 30 37 CAT 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

REPORT SOURCE L 6 0 5 0 0 0 2 6 7 7 0 2 0 9 7 9 8 0 4 0 9 8 1 9

60 81 DOCKET NUMBER 88 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While the plant was in a shutdown condition and the semi-annual loss of outside  
0 3 electrical power test was being performed, diesel generator 1A output circuit breaker  
0 4 did not close. This is a degraded mode of LCO 4.6.1(3) and is reportable per Fort St.  
0 5 Vrain Technical Specification AC 7.5.2(b)2. There was no affect on public health or  
0 6 safety. No accompanying occurrence. Redundant system available and operable.  
2 7 Similar report RO 77-31.  
0 8

SYSTEM CODE E D (11)		CAUSE CODE E (12)		CAUSE SUBCODE A (13)		COMPONENT CODE C R 1 B R K (14)				COMP. SUBCODE A (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 0 5 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE X (20)		REVISION NO. 1 (21)		ACTION TAKEN C (22)		FUTURE ACTION D (23)	
EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 0 (26)		ATTACHMENT SUBMITTED Y (27)		NPRD-4 FORM SUB. N (28)		PRIME COMP. SUPPLIER N (29)		COMPONENT MANUFACTURER I 2 0 2 (30)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (31)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 One ITE Model K-1600 circuit breaker failed to close. Breaker replaced with an equivalent spare. The breaker was disassembled and inspected. The grease used in the breaker was found to have dried out due to the high ambient temperature. The breaker was relubricated and returned to service. A maintenance program was established to disassemble and relubricate these breakers every six months.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (D) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) N/A

METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Surveillance Test

ACTIVITY CONTENT (1) 6 (Z) (33) RELEASED OF RELEASE (Z) (34) AMOUNT OF ACTIVITY (35) N/A

LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	0	37	38
		0	Z	N/A

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	3	0	0
7	8	0	0
9	11	40	N/A
12			

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 3 Z (42) N/A

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44)	N/A	(45)		

NRC USE ONLY

NAME OF PREPARER

PHONE: (303) 785-2224