



RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Docket No. 50-36

License No. PF-3

Serial No. 716

May 28, 1981

Director of Nuclear Reactor Regulation
Attention: Mr. John F. Stolz
Operating Reactor Branch No. 4
Division of Operating Reactors
United States Nuclear Regulatory Commission
Washington, D.C. 20555



Dear Mr. Stolz:

This letter is to document a partial response to NUREG-0737, Clarification of TMI Action Plan Requirements, for Davis-Besse Nuclear Power Station Unit 1 (DB-1). Item III D.3.4 deals with Control Room Habitability Study.

The analysis shows that no substance stored on or offsite nor shipped on State Highway Route 2, a medium to heavily traveled highway adjacent to the westerly site boundary, will cause unacceptable hazards in the control room for a catastrophic failure of the storage or shipping container.

Very truly yours,

RPC/GAB:lab

Enclosure

cc: DB-1 NRC Resident Inspector

A046
3
1/1

81060405834

P