

LICENSEE EVENT REPORT

LER 81-11/3L

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	4	57	CAT	58	5

CON'T

REPORT SOURCE 0 1 7 8

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE 0 5 0 7 8 1 3 0 6 0 3 8 1 9

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation of the Reactor Water Cleanup System, routine operator sur-
0 3 | veillance discovered a small leak in a 1" X 3/4" socket weld reducing fitting in
0 4 | the tube-side drain line of Regenerative Heat Exchanger E-15-1A upstream of valve
0 5 | V12-41A. There were no consequences adverse to the public health and safety as a
0 6 | result of this event. Similar previous occurrences were reported to the Commission
0 7 | as LER 79-01, 80-37 and 80-41.
0 8 |

0 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE								
7	8	C	G	E	D	P	I	P	E	X	A	Z	11	12	13	14	15	16	17	18	19	20
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
21	22	8	1	0	1	1	0	3	L	0												
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
A	Z	Z	Z	0	0	0	N	Y	A	E	0	6	5									
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47								

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Previous incidents of cracking in this system are being analyzed by an independent
1 1 laboratory to determine the failure mode, and the results of this analysis will be
1 2 reported to the Commission in an update to the applicable LER's. Immediate
1 3 corrective action in this case was to replace the degraded fitting with an
1 4 identical spare.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	NA	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	1	0	0	34	NA	35
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40			NA	41
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42					NA	43
PUBLICITY		ISSUED		DESCRIPTION					
2	0	X	44					Daily Status Phone (5/7, 8 and 11/81)	45
								NRC USE ONLY	

NAME OF PREPARER W. P. Murphy

PHONE: (802) 257-7711

8106080 297