

LICENSEE EVENT REPORT

LER 81-13/3L

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE							14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT 58				

CON'T

REPORT SOURCE 01 605000271705058180604819

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During weekly environmental air sample collections on 5/5 and 5/13/81, it was
0 3 | discovered that continuous samples were not being drawn at station AT 1.4 as requir-
0 4 | ed by T. S. Table 3.9.1. During the above periods, plant stack release levels were
0 5 | normal and past experience has shown them to be undetectable by environmental air
0 6 | sampling. It is therefore concluded that these incidents were of no consequence, or
0 7 | potential consequence, to the health and safety of the public. Similar occurrences
0 8 | were reported as RO 80-21, 81-05 and 81-09.

SYSTEM CODE B B		CAUSE CODE B		CAUSE SUBCODE B		COMPONENT CODE P U M P X X				COMP. SUBCODE C		VALVE SUBCODE Z					
11		12		13		14				15		16					
9 10		11		12		13 14 15 16 17 18				19		20					
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 1 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0									
21 22		23 24 25 26		27 28 29		30 31		32									
ACTION TAKEN C		FUTURE ACTION C		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRO-4 FORM SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER X 9 9 9	
18 19		20		21		22		23		24		25		26		27	
33 34		35		36		37 38 39 40		41		42		43		44 45 46 47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Defective windings caused the pumps to cycle on and off under field conditions. The

1 1 failed pumps were replaced by other pumps which bench tested satisfactorily. Pumps

1 2 of a different manufacturer have been ordered and will be installed and evaluated

1 3 for possible permanent use.

1 4 7 8 9
FACILITY STATUS
1 5 9 E 28
% POWER
0 9 9 12 29
OTHER STATUS 30 NA
METHOD OF DISCOVERY
B 31
DISCOVERY DESCRIPTION 32 Technician Observation
80 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 10 Z 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	37	2	38	NA		

PERSONNEL INJURIES		DESCRIPTION
1	8	NA

7		8		9		10		11		12		
LOSS OF OR DAMAGE TO FACILITY												
TYPE		DESCRIPTION										
1	9	Z	(42)	NA								

7 8 9 10

PUBLICITY (45)

ISSUED (44) DESCRIPTION NA

7 8 9 10 68 69 70

NRC USE ONLY

NAME OF PREPARER Warren P. Murphy

PHONE: (802) 257-7711

8106090472