

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 1 | L | Q | A | D | 2 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 37 CAT 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 2 6 5 7 0 2 0 2 8 1 8 0 2 1 3 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 2215 while performing HPCI valve operability test, outboard steam isolation

0 3 | valve M0-2-2301-5 was closed but would not re-open. RCIC had been made inoperable

0 4 | prior to this time. Consequently, an immediate Reactor shutdown was started in

0 5 | accordance with Technical Specification 3.5.E.3. and 3.5.E.3. Auto-pressure relief

0 5 | and all low-pressure ECCS were operable.

217

376

7 8 9 80

SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE V A L V O P 14		COMP. SUBCODE B 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 8 1 17		EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO. 0 0 3 24 26		OCCURRENCE CODE / 27		REPORT TYPE T 30		REVISION NO. 0 32	
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT B 20		SHUTDOWN METHOD A 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER L 2 0 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Valve M0-2-2301-5 had been demonstrated operable in the cold condition on February 1, 1981. However, in the hot condition more torque was required to lift the valve disc off the seat. The valve limit switches were adjusted and the valve demonstrated operable on February 2, 1981.

1 4
7 8 9 80

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 5 E 28 0 2 4 29 NA A 31 Routine Surveillance 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) AMOUNT OF ACTIVITY (35)

7 8 9 10 11 44

NA

LOCATION OF RELEASE (36)

45 46

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	(40) NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52																																																									

10
 PUBLICITY
 8106090677
 ISSUED DESCRIPTION (45)
 2 1
 N (14) NA
 NRC USE ONLY

D Hannum

PHONE: 309-654-2241, ext. 177