

1750 Chestnut Street Tower II

June 19, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-260/81026

The enclosed report provides details concerning one inservice inspection ultrasonic examination performed on unit 2 piping which did not receive evaluation required to meet TVA's commitment to 1971 edition, summer 1971 Addenda of Section XI. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.b(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IE22  
s  
1/1

8106290 053

S

POOR ORIGINAL