

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A L J M F 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 53

REPORT SOURCE

L 6 0 5 0 0 0 3 6 4 7 0 5 2 6 8 1 3 0 6 2 5 8 1 3

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

At 0500 on 5/26/81, R-29B (Plant Vent Stack Effluent Monitor) was declared inoperable when the pump was found tripped. Tech. Spec. 3.3.3.1, in part, requires R-29B to be operable. Tech. Spec. 3.3.3.1 action statement requirements were met. Health/safety of the public was not affected by this occurrence.

SYSTEM CODE

CAUSE CODE

CAUSE SUBCODE

COMPONENT CODE

COMP. SUBCODE

VALVE SUBCODE

LER/RO REPORT NUMBER

EVENT YEAR

SEQUENTIAL REPORT NO.

OCCURRENCE CODE

REPORT TYPE

REVISION NO.

ACTION TAKEN

FUTURE ACTION

EFFECT ON PLANT

SHUTDOWN METHOD

HOURS

ATTACHMENT SUBMITTED

NPRC-4 FORM SUB.

PRIME COMP. SUPPLIER

COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Incident is attributable to a dirty filter. The filter was replaced and R-29B was returned to service at 0540 on 5/26/81. The frequency for performing preventative maintenance on this filter will be evaluated.

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASED OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

PERSONNEL INJURIES

NUMBER

DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY

TYPE

DESCRIPTION

PUBLICITY

ISSUED DESCRIPTION

8106800309

5

NRC USE ONLY