

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 5 2 3 8 1 8 0 6 2 2 8 1 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 Action Statement 3.4.5.b was entered at 1551 hours on May 23, 1981, when valve  
0 3 position indication could not be obtained when valve 2PR6 was repositioned. The  
0 4 valve was declared inoperable and power to the valve operator was removed.  
0 5  
0 6  
0 7  
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
C J 11 E 12 B 13 V A L V E X 14 E 15 D 16  
7 8 9 10 11 12 13 18 19 20  
17 LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 1 0 2 7 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
E 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 L 25 V 0 8 5 26  
33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Maintenance Department Work Order #MD947233 was issued to investigate and repair  
1 1 failed valve 2PR6. The motor operator limit switch was adjusted and 2PR6 was tested  
1 2 satisfactorily. Action Statement 3.4.5.b was terminated at 2305 hours on June 11, 1981.  
1 3  
1 4

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
E 28 0 0 0 29 N/A A 31 Personnel Observation  
7 8 9 10 12 13 44 45 46 80  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 N/A N/A  
7 8 9 10 11 44 45 80  
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 N/A  
7 8 9 11 12 13 80  
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 N/A  
7 8 9 11 12 80  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 N/A  
7 8 9 10 80  
2 0 PUBLICITY ISSUED DESCRIPTION  
N 44 N/A  
7 8 9 10 80

8107060274 810622  
PDR ADOCK C5000311  
S PDR

IER J. J. Espey

PHONE 609-935-0998