

New Hampshire Yankee

Ted C. Feigenbaum
Senior Vice President and
Chief Operating Officer

NYN- 90015

January 23, 1990

United States Nuclear Regulatory Commission
Washington, DC 20555

Attention: Document Control Desk

References: (a) Facility Operating License NPF-67, Docket No. 50-443

(b) NHY Letter NYN-89061, dated May 12, 1989, "Inadequate Core Cooling (ICC) Monitoring System, NUREG-0737, Item II.F.2 Implementation" G. S. Thomas to USNRC.

Subject: Completion of Inadequate Core Cooling Monitoring System Enhancements, NUREG-0737, Item II.F.2


Gentlemen:

In Reference (b), New Hampshire Yankee (NHY) submitted implementation information for the Inadequate Core Cooling Monitoring System as required by Safety Evaluation Report Supplement No. 5. It also indicated that minor firmware conditions requiring system enhancements which were identified during testing would be implemented prior to exceeding 5% power. Notification is hereby provided that the requisite enhancements to the Inadequate Core Cooling Monitoring System have been installed and tested and that the system is operable.

New Hampshire Yankee requests that the implementation of the Inadequate Core Cooling Monitoring System be reflected in the next supplement to the Safety Evaluation Report.

Should you have any questions regarding this letter please contact Mr. Terry Harpster Director of Licensing Services at (603) 474-9521 extension 2765.

Very truly yours,



Ted C. Feigenbaum

9001300431 900123
PDR ADLOCK 05000443
P FDC

United States Nuclear Regulatory Commission
Attention: Document Control Desk

January 23, 1990
Page 2

cc: Mr. William T. Russell
Regional Administrator
United States Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Mr. Victor Nerses, Project Manager
Project Directorate I-3
United States Nuclear Regulatory Commission
Division of Reactor Projects
Washington, DC 20555

Mr. Noel Dudley
NRC Senior Resident Inspector
P.O. Box 1149
Seabrook, NH 03874