


THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201

May 6, 1981
QA-1422

E. A. BORGMANN
SENIOR VICE PRESIDENT

U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Attention: Mr. G. Fiorelli, Chief
Reactor Construction & Engineering
Support Branch

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT I
10CFR50.55(e) M-28, YUBA HEAT TRANSFER CO.,
FUEL POOL HEAT EXCHANGERS, CONSTRUCTION PERMIT
CPPR 88, DOCKET NO. 50-358, W. O. 57300-957
JOB E-5590

Gentlemen:

On April 6, 1981, the NRC Site Senior Resident Inspector was notified by phone of a possible 10CFR50.55(e) condition regarding tube failures in the Fuel Pool Heat Exchangers which appeared to be due to an excessive tube vibration situation.

Cincinnati Gas & Electric Co. is continuing to investigate this item. The present status of this investigation indicates that the item is not reportable under 50.55(e).

A final report will be submitted within sixty (60) days.

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

E. A. Borgmann for E. A. Borgmann

By

E. A. BORGMANN
SENIOR VICE PRESIDENT

DJS:ec

cc: NRC Resident Inspector
Attn: F. T. Daniels
NRC Office of Inspection & Enforcement
Washington, D. C. 20555

S

8105120 351

13019
S1/0