

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																
7	8	9						14						15						25						26						30						57						58	
		LICENSE CODE												LICENSE NUMBER												LICENSE TYPE																			

CON'T

REPORT SOURCE 0 1 7 8

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOC# ET NUMBER 5 0 0 0 0 3 1 1 7 0 5 3 0 8 1 8 0 6 2 9 8 1 9

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During start-up operations on May 30, 1981, No. 21 Auxiliary Feed Pump outboard
0 3 | bearing went into high temperature alarm and was removed from service. Investi-
0 4 | gation of the alarm, found the outboard bearing and seal assembly had failed. At
0 5 | 0500 hours the Auxiliary Feed Pump was declared inoperable and Action Statement
0 6 | 3.7.1.2.a was entered. This occurrence constituted operation in a degraded mode
0 7 | IAW Technical Specification 6.9.1.9.b.

0	8		8
---	---	--	---

SYSTEM CODE C H 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE P U M P X X 14		COMP. SUBCODE B 15		VALVE SUBCODE Z 16							
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 3 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0									
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER L 25		COMPONENT MANUFACTURER 8 5 8 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The radial bearing, thrust bearing, mechanical seal, and rotating assembly were

1 1 replaced. The No. 21 Auxiliary Feed Pump was tested satisfactorily. The Action

1 2 Statement was terminated at 0512 hours, on June 2, 1981.

1	3	
---	---	--

1	4	
---	---	--

[illegible]

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z 33 Z 34 NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES			
NUMBER		TYPE	DESCRIPTION
1	7	000 (37)	Z (38) NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40
		NA	

7		8	9	11		12			
		LOSS OF OR DAMAGE TO FACILITY						(43)	
		TYPE		DESCRIPTION					
1	9	2	(42)	NA					

ISSUED		DESCRIPTION		NRC USE ONLY										
2	0	N	44	NA										

NRC USE ONLY

J. J. Espey

PHONE: 609-935-0998