

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

N J O C P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 LICENSEE CODE 15 LICENSE NUMBER 25 LICENSE TYPE 30 CAT 58

7 8 7 8 9
REPORT SOURCE L 6 0 5 0 0 0 2 1 9 7 0 6 1 7 8 1 8 0 7 0 1 8 1 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

Secondary Containment was broken when both reactor building railroad airlock doors were open together. The inner door sprung open at the top caused by a broken latch during transfer of the Standby Gas Treatment System to normal ventilation. The outer door was immediately secured. The event was terminated within five minutes.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
S	A	D		X		P	E	N	E	T	R	C	Z		
9	10	11	12	13	14	15	16	17	18	19	20	21	22		
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
3	1	0	2	5	0	1	T	0							
21	22	23	24	25	26	27	28	29	30	31	32				
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
B	B	4	Z	0	0	0	N	N	Z	Z	9	9	9		
33	34	35	36	37	38	39	40	41	42	43	44	45	46		

The cause of the event is attributed to failure of the top inner door latch permitting the door to partially open and failure of the operator to start the Reactor Building supply fan after starting the exhaust fan. The operators will be instructed in the proper operation of the airlock doors and a procedure revision will be made to prevent recurrence.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	(28)	0	9	2	(29)	NA	
								A	(31)
								Observation	(32)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 2 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	(37) Z	(38) NA	(39)		

[illegible]

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
										LOSS OF OR DAMAGE TO FACILITY																																																																																									
TYPE										DESCRIPTION																																																																																									

1 9 Z 42 NA
7 8 9 10
PUBLICITY
B107130468 B10701
PDR ADPOCK 05000218
NRC USE ONLY

ISSUED DESCRIPTION (45) NA S PDR

2	0	N	(44)
---	---	---	------

68 69 70

(600) 602-6085

Elwood I. Riggle

[illegible]