

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)



Commonwealth Edison

DEVIATION REPORT

 DVR NO. _____
 STA UNIT YEAR NO.
 D-12 - 2 - 81 - 61

PART 1 TITLE OF DEVIATION

Loss of One Vacuum Breaker Indication

OCCURRED

6-7-81

13:45

DATE

TIME

SYSTEM AFFECTED 1600

PLANT CONDITIONS

Primary Containment

MODE Run

PWR(MWT) 1143

LOAD(MWE) 318

TESTING

☒ YES ☐ NO

YES NO

DESCRIPTION OF EVENT

During Suppression Chamber to Drywell Vacuum Breaker Operability Test, DOS 1600-9,
 vacuum breaker 2-1632-D right limit switch failed to cause Alarm 902-4-G-14 or cause
 the 1 :al light to go out.

DESCRIPTION OF CAUSE

Bad switch.

OTHER APPLICABLE INFORMATION

Left side switch works.

EQUIPMENT ☒ YES
FAILURE ☐ NO

DR NO.

-

WR NO.

D14091

R. Weidner

RESPONSIBLE SUPERVISOR

6-7-81

DATE

PART 2 OPERATING ENGINEERS COMMENTS

Drywell vacuum breaker was physically verified to be closed immediately.

TYPE OF DEVIATION
REPORTABLE OCCURRENCE☐ 14 DAY ☐ 10CFR21☒ 30 DAY NOTIFICATION
6.6.B.2.b.EVENT OF POTENTIAL
PUBLIC INTEREST☐TECH SPEC
VIOLATION☐NON-REPORTABLE
OCCURRENCE☐ANNUAL
REPORTINGYES ☒NO ☐SAFETY-
RELATED
WR ISSUEDYES ☒NO ☐REPORTABLE OCCURRENCE
NUMBER

81-37/03L-0

ACTION ITEM NO.

PROMPT ON-SITE NOTIFICATION

D. J. Scott

6-8-81

08:00

TITLE

DATE

TIME

TITLE

DATE

TIME

24-HOUR NRC NOTIFICATION

☒ TPH

Mike Jordan

6-8-81

0900

REGION III

DATE

TIME

☐ TGM

REGION III & DOL

DATE

TIME

PROMPT OFF-SITE NOTIFICATION

F. A. Palmer

6-8-81

12:50

TITLE

DATE

TIME

TITLE

DATE

TIME

RESPONSIBLE COMPANY / OFFICER INFORMED OF 10CFR21
CONDITIONS AND THEIR REPORT TO NRC

TITLE

DATE

TIME

REVIEW AND COMPLETED

J. W. Wujciga

6-8-81

OPERATING ENGINEER

DATE

ACCEPTANCE BY STATION REVIEW
AS REQUIRED

DATE

RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

J. O. Ciesla

7-2-81

7/2/81

R. W. Pagan

STATION SUPERINTENDENT

7/2/81

DATE